

## **MAZDA RX-8 FUEL PUMP PIPE RECALL**

WASHINGTON, DC (June 7, 2017) – Mazda North America Operations announced today that it is recalling certain model year 2004-2008 RX-8 vehicles.

Heat from the engine and the exhaust may cause the main fuel pump pipe to crack. If the fuel pump pipe cracks, fuel may leak, increasing the risk of a fire.

There have been no reports of accidents or injuries.

Approximately 69,447 vehicles are affected.

Mazda North American Operations is headquartered in Irvine, California, and oversees the sales, marketing, parts and customer service support of Mazda vehicles in the United States and Mexico through more than 600 dealers. Operations in Mexico are managed by Mazda Motor de Mexico in Mexico City. For more information on Mazda vehicles, including photography and B-roll, please visit the online Mazda media center at [InsideMazda.MazdaUSA.com/Newsroom](http://InsideMazda.MazdaUSA.com/Newsroom).

# # #

Contact:

Tamara Mlynarczyk, Mazda North American Operations, 202-467-5092

---

<https://news.mazdausa.com/2017-06-07-Mazda-RX-8-Fuel-Pump-Pipe-Recall>