

STATEMENT ON SAFETY RECALL 7124J

INOPERABLE DEFROSTER AND SEAT BELT WARNING LIGHT ON CERTAIN CX-90 AND CX-70 VEHICLES

WASHINGTON, DC. (Nov. 1, 2024) – Mazda North American Operations (MNAO), on behalf of Mazda Motor Corporation, has filed a safety noncompliance defect notification with the National Highway Traffic Safety Administration (NHTSA) for a concern which exists on certain 2024-2025MY CX-90 and 2025MY CX-70 vehicles.

Due to improper software programming of the Dash Electrical Supply Unit (ESU), an error may occur during vehicle startup. If this occurs, multiple warning messages will be displayed in the instrument cluster, and the defroster, seat belt warning, and 360° view monitor functions may not operate properly. Furthermore, the engine warning light may be illuminated, and the PHEV high-voltage battery cooling system may not function as intended. If the defroster, seat belt warning and 360° camera view monitor functions do not work, this can increase the risk of a crash.

There have been no reports of any accidents or injuries due to the defect.

Approximate number of vehicles affected in the U.S. and U.S. Territories:

2024-2025MY CX-90 – 70,974 units

2025MY CX-70 – 9,943 units

Affected owners will be notified by U.S. Mail.

Please check [mazdarecallinfo.com](https://www.mazdarecallinfo.com) or [nhtsa.gov](https://www.nhtsa.gov) for the latest updates. To see if your vehicle is involved in a safety recall visit www.mazdarecallinfo.com or [nhtsa.gov/recalls](https://www.nhtsa.gov/recalls).

About Mazda North American Operations

Proudly founded in Hiroshima, Japan, Mazda has a history of sophisticated craftsmanship and innovation, and a purpose to enrich life-in-motion for those it serves. By putting humans at the center of everything it does, Mazda aspires to create uplifting experiences with our vehicles and for people. Mazda North American Operations is headquartered in Irvine, California, and oversees the sales, marketing, parts and customer service support of Mazda vehicles in the United States, Canada, Mexico and Colombia through approximately 795 dealers. Operations in Canada are managed by Mazda Canada Inc. in Richmond Hill, Ontario; operations in Mexico are managed by Mazda Motor de Mexico in Mexico City; and operations in Colombia are managed by Mazda de Colombia in Bogota, Colombia. For more information on Mazda vehicles, including photography and B-roll, please visit the online Mazda media center at news.mazdausa.com.

Follow @MazdaUSA on social media: Facebook, Instagram, X, YouTube, and Threads.

<https://news.mazdausa.com/2024-11-1-STATEMENT-ON-SAFETY-RECALL-7124J>